



Technical Bulletin # TCB27

Transmission: 6R80

Subject: Torque Converter Shudder 25-45 MPH

Application: Ford

Issue Date: September, 2012

Torque Converter Shudder 25-45 MPH

Some 2010 Ford F150 trucks equipped with 4.6L engine and a 6R80 transmission, may experience a torque converter shudder during light throttle acceleration between 25-45 mph.

This same complaint may be felt during downshifts followed by light throttle tip-in. Ford Motor Co. has released a new calibration to correct this concern. Refer to FMC TSB # 10-25-13 for details.

6R80 Transmission

